


# **Comments on Army's Proposed Plans for Remediation of Groundwater at the Longhorn Army Ammunition Plant**


**Community Meeting  
Karnack Community Center**

**May 20, 2010**

**George Rice**



LHAAP Sites






 U.S. ARMY CORPS OF ENGINEERS  
 TULSA DISTRICT  
 TULSA, OKLAHOMA


Figure 1  
 Shallow Groundwater Wells at LHAAP-35B  
 LONGHORN ARMY AMMUNITION PLANT  
 KARNACK, TEXAS

Site LHAAP-35B(37), Shallow Groundwater Zone




Site LHAAP-50, Intermediate Groundwater Zone

# Site 67, Well 67WW01



# Site 35A(58), Well LHSMW07



# Site 46, Well LHSMW19

